







THE KATHMANDU VALLEY PRESERVATION TRUST

## THE RESTORATION OF THE BHANDARKHAL GARDEN & WATER ARCHITECTURE

AT PATAN DARBAR PALACE COMPLEX - A UNESCO WORLD HERITAGE SITE



The collapsed East wing of Sundari Chowk Palace | April 25, 2015 The East wing which was built in 1936 was the only palace structure that collapsed. All other and recently restored palace buildings survived the earthquake.




View over the Tank towards the Palace Complex | April 25, 2015 Immediately after the first earthquake people sought refuge in the garden. For over two months more than 50 families who had lost their houses were living in tents in the garden.





Installation of the new water line | 2015




**Histocic water supply channel** | 2015 The interlocking terracotta channels were carefully cleaned and sealed with mud and brick above.




Tusha hiti water spout | 2009 In 2009 the historic water line dating back to the 17th century was still providing clean water even though it dried up during the spring months.



**Tusha hiti water spout** | 2015 Six years later water supply has almost completely stopped. The little water that occaionally runs is heavily polluted.



**Tunneling under the East wing** The new water line was installed at a depth of 3 meters.





## KATHMANDU VALLEY PRESERVATION TRUST

36 West 25th Street - 17th Floor New York, NY 10010, USA TEL: 212 727 0074

P.O. Box 13349, Kathmandu, NEPAL TEL: (977 1) 55 46 055

kvptnepal.org

